



# ELECTRIC MACHINES – UNILAB – 1 kW



## ACCESSORIES

### STARTING RHEOSTAT



#### DL 1017RHD

Step-variable rheostat for the half torque starting of the dc motors of the laboratory.

### STARTING RHEOSTAT



#### DL 1017RHD3

Step-variable three-phase rheostat for the half torque starting of the slip ring motors of the laboratory.

### EXCITATION RHEOSTAT



#### DL 1017RHE

Suitable for the shunt excitation of the dc machines and of the synchronous machines of the laboratory.

### EXCITATION RHEOSTAT



#### DL 1017RHES

Suitable for the series excitation of the dc machines of the laboratory.

### STARTING AND SYNCHRONIZATION UNIT



#### DL 1022RHD3

Starting rheostat for the three-phase slip ring induction motors and excitation device for the synchronization of the motor with the mains.