TRANSMITTER

Model: TR-CLP1A4

ISO-9001, CE, IEC1010









The Art of Measurement

2,000 A DC/AC Clamp TRANSMITTER

Model: TR-CLP1A4

Measure	Range 1 :	Range 2 :
Range	0 - 200 A	0 - 2000 A
	* Isolated	
Output	4 - 20 mA	
	Range 1 :	Range 2 :
	0 A = 4 mA	0 A = 4 mA
	100 A = 12 mA	1000 A = 12mA
	200 A = 20 mA	2000 A = 20mA
External	ZERO VR	
Adjustment	SPAN VR	
Power	90 - 260 ACV	
Supply	50 Hz/60 Hz	
Operation	0 - 50 ℃	
Temperature	32 - 122 °F	
Operation	Less than	
Humidity	80 %RH	
Accessory	200/2000 A inductive	
Included	DC/AC clamp probe	
Mounting	Din rail or Wall	
Case	ABS plastic	
Others	Separate 200/2000 A inductive	
	DC/AC clamp	

^{*} Appearance and specifications listed in this brochure are subject to change without notice.