



ELECTRIC MACHINES – EUROLAB – 0.3 kW

ACCESSORIES



STARTING RHEOSTAT



DL 30200RHD

Step-variable rheostat for the half torque starting of the dc motors of the laboratory

STARTING RHEOSTAT



DL 30120RHD3

Step-variable three-phase rheostat for the half torque starting of the slip ring motors of the laboratory

EXCITATION RHEOSTAT



DL 30205

Suitable for the shunt excitation of the dc machines and of the synchronous machines of the laboratory

EXCITATION RHEOSTAT



DL 30206

Suitable for the series excitation of the dc machines of the laboratory