TRUE RMS DMM

Model: DM-9961 *ISO-9001, CE, IEC1010*



Features:

- * Heavy duty CAT III-1000V category.
- * 4000 counts, auto/manual range.
- * Large LCD, digit height 23 mm.
- * ACV, ACA, DCV, DCA, ohms, continuity buzzer.
- * Hz/Duty cycle, Capacitance, diode.
- * Data hold, Relative, range hold.
- * High input impedance for mV range.
- * 10 Amp. current with fuse protection.
- * Size: 194 x 89 x 40 mm.



Model: DM-9961



The Art of Measurement

True RMS AUTO RANGE MULTIMETER

CAT III-1000 V category, Auto range, REL, Capacitance Hz, Duty, ACV, ACA, DCV, DCA, Ohms

Model: DM-9961

FEATURES					
* True RMS ACV, ACA measurement	* 4000 counts A/D, high resolution.				
* Meet IEC 1010 CAT III 1000 V safety requirement.	* Both 10 A, mA, uA current are build fuse for safety				
* Large LCD display with measurement unit.	consideration.				
* Multi function measurement. DCV, ACV, DCA, ACA,	* 10 M ohm impedance for voltage circuit.				
Resistance, Capacitance, Frequency, Duty, Diode,	* Operates from one DC 9V battery,				
Continuity beeper.	* Built-in overload protection for most ranges.				
* Data hold.	* Uses durable, long-lasting components, enclosed in				
* Relative measurement.	strong, light weight ABS-plastic housing.				
* Auto range with manual range selection.	* Full line optional adapters : Clamp adapter,				
* When make the ACV, ACA measurement, it	Tachometer adapter, Pressure adapter, Humidity				
also can measure the signal frequency, % duty at	Adapter, Sound level adapter, Anemometer adapter,				
the same time.	Light adapter, EMF adapter.				

GENERAL SPECIFICATIONS						
Display	65 mm x 48 mm large LCD display with bar graph indicator.	Operating humidity	Max. 80% RH.			
Measurement	DCV, ACV, DCA, ACA, Resistance, Capacitance, Frequency, Duty,	Power supply	006P DC 9V battery.			
A/D counts no.	Diode, Continuity beeper. 4000 counts.	Power consumption	Approx. DC 1.7 mA.			
Range selection	Auto range with manual range selecting.	Dimension	185 x 88 x 40 mm (7.3 x 3.5 x 1.6 inch)			
Special function	Relative measurement, Data hold.	Weight	350 g/0.77 LB.			
Data hold	To freeze the display reading on the LCD display.	Accessories Included	Red and Black Test Leads (CAT III 1KV Test Leads) 1 Set			
Power On/Off management	Auto power of or manual power off. @ Details please refer page 8		0.5 Amp Spare Fuse			
Relative measurement	To offset the measurement value.	Optional accessories	Full line adapters : ACA/DCA current adapter,			
Polarity	Automatic Switching, " - " indicates negative polarity.		Tachometer adapter, Humidity adapter, Pressure adapter,			
Zero adjustment	Automatic.		Light adapter, EMF adapter,			
Sampling time	Approx. 0.5 to 1 second.		Sound level adapter,			
Operating Temp.	0 to 50 °C (32 to 122 °F),		High voltage probe. Soft carrying case			

ELECTRICAL SPECIFICATIONS (23±5°C)							
DC Voltage		Capacitance					
Range	400.0 mV /4 V/40 V/400 V/1000 V	Range	40 nF/400 nF/4 uF/40 uF/100 uF				
Resolution	0.1 mV /1 mV /10 mV /100m V/1 V	Resolution	10 pF/0.1 nF/1 nF/10 nF/0.1 uF				
Accuracy	± (0.5%+2d)	Accuracy	± (3%+1d)				
Input impedance	10 M ohm.	, ,					
Over load	± 500 DCV, 350 ACV - 200 mV range.	Frequency					
protection	± 1000 DCV, 1000 ACV - other ranges.						
•		1	400 KHz/4 MHz				
AC Voltage (True RMS)		Resolution 0.001 Hz/0.01 Hz/0.01 Hz/0.001 KHz/0.01 KHz		z/0.001 KHz/0.01 KHz			
Range	400.0 mV /4 V/40 V/400 V/1000 V		0.1 KHz/0.001 MHz				
Resolution	0.1 mV /1 mV /10 mV /100m V/1 V	Accuracy	± (0.5%+2d)				
Accuracy	± (1%+2d)	Sensitivity	Min. 1.5 V rms, Max. 5 V rms.				
,	* Spec. are tested under 50/60 Hz.						
Input impedance	10 M ohm.	Duty	Dutv				
Over load	± 500 DCV, 350 ACV - 200 mV range.	Range	1 % to 99 %				
protection	± 1000 DCV, 1000 ACV - other ranges.	Resolution	0.1 %				
		Accuracy	± 1% duty				
AC Current (True RMS)		Measuring signal	Function switch set to " Hz " :				
DC Current		and level	2 Vp-p to 5 Vp-p,				
Range	10 A/400 mA/40 mA/4000 uA/400 uA		square wave 10 KHz max.				
Resolution	10 mA/0.1 mA/0.01 mA/1 uA/0.1 uA		Function switch set to "ACV", "ACA" :				
Accuracy	400 mA/40 mA/4000 uA/400 uA :		50 Hz to 500 Hz				
-	± (0.5%+2d)						
	10 A :	<i>OHMS</i>					
	± (1.5%+2d)	Range	400/4 K/40 K/400 K/4 M/40 M ohm				
	* ACA spec. are tested under 50/60 Hz.	Resolution	0.1/1/10/100/1 K/10 K ohm				
Over load	10A range: 10A fuse.	Accuracy	400 ohm	± (0.5%+2d)			
protection	uA, mA range : 500 mA fuse.		4K/40K/400K/4 M				
			40 M	± (2%+5d)			
Diode (Forward voltage, VF)		Over load	± 350 DCV, 350 ACV				
Range	4 V DC.	protection					
Resolution	0.001 V.						
Accuracy	± (0.5%+2d)	Continuity Beeper Beeper will sound if measured resistance less than 20 ohm.					
* ^	cations listed in this brochure are subject to change with			0005-DM0061			

^{*} Appearance and specifications listed in this brochure are subject to change without notice.